

Grade B and C have top boards of different measurements.



Grade B might have damage or cracked stringers but another piece of wood is added for support



Grade C might have stringers incomplete but another piece of wood is added for support.